

Section 1	Identification
Product Name: Synonyms:	 CenterLine[®] RWMA Class 2 Copper Resistance Welding Electrodes Electrodes, adapters and holders used for resistance welding, which contain chromium, including: C18150 (CuCrZr) and C18200 (CuCr) alloys Material and miscellaneous components of A2/2 (ISO 5182) and A2/1 (ISO 5182) copper alloys.
Recommended Use	e: Electrodes and associated components are generally used without modification to perform one of the resistance welding process variations including: spot, projection, seam, upset (i.e., butt), and flash welding; or other associated processes such as hot upset, resistance brazing, or resistance parting. These components generally conduct electrical current and transmit force to the workpiece(s).
Manufacturer: General Informatio Emergency:	CenterLine (Windsor) Ltd, 415 Morton Drive, Windsor, Ontario N9J 3T8, Canada n: T:519-734-8464 / F:519-734-2000 / Email: info@cntrline.com 800-268-8184 / 519-734-0080
Section 2	Hazard(s) identification

Section 2 Hazard(s) identification

During normal operation and usage, this non-combustible, non-reactive, solid material article does not present inhalation, ingestion, or chemical hazards. Electrodes that this SDS concerns will require periodic maintenance or replacement, during which exposure to adhered hazardous contamination is possible. When this article is machined or otherwise modified by the user, dusts or fumes may be created, which may be potentially hazardous if the exposure limits described in Section 3 are exceeded.

Lead and hexavalent chromium, which may be present in fume, are classed as carcinogens.

Section 3 Composition/information on ingredients

Where present, listed constituents are dispersed in a solid alloy matrix. Concentration percent by weight (% WT) must not be interpreted as a specification for a particular product.

MATERIAL OR COMPONENT	CAS. NO.	EINECS NO.	% WT	OSHA-PEL ^a	ACGIH-TLV ^a
MAY CONTAIN THE FOLLOWING:					
1. Copper	7440-50-8	231-159-6	Balance	0.1 mg/m ³	0.2 mg/m ³
2. Chromium	7440-47-3	231-157-5	< 1.5	0.5 mg/m ³	0.5 mg/m ³
3. Zirconium	7440-67-7	231-176-9	< 0.25	5 mg/m³	5 mg/m ³
4. Iron-oxide	1314-37-2	215-570-8	<0.1	10 mg/m ³	5 mg/m ³
5. Silicon	7440-21-3	231-130-8	<0.1	5 mg/m³	10 mg/m ³
6. Lead	7439-92-1	231-100-4	<0.05	0.05 mg/m ³	0.05 mg/m ³

^a Other national or regional values or measures of exposure may be required at the point of use.

Section 4 First-aid measures

Show this SDS to those administering medical attention or treatment.

Inhalation: If breathing has stopped, perform artificial respiration and obtain medical aid immediately. If breathing is difficult, provide fresh air and seek medical attention as soon as possible.

Skin: Cuts or abrasions should be treated promptly with thorough cleansing of the affected area. Wash the skin using soap or mild detergent and water. Get medical attention if irritation develops and persists.

Eyes: Eye injuries from solid particles should receive immediate medical attention. Dust may be flushed from eyes immediately with large amounts of water, lifting the lower and upper lids occasionally; seek medical attention.

Ingestion: If the product or dust is swallowed, seek immediate medical attention or advice. Do not induce vomiting.

Section 5 Fire-fighting measures

Suitable extinguishing media: This solid material is noncombustible. Use extinguishing media appropriate to the



surrounding fire.

Special Fire Fighting Procedures: Not applicable

. .

grind	a explosion hazard: A fire or explosion hazard is not likely but, is possible if dusts generated by ling are present in certain combinations of particle size, dispersion, concentration, and strong ignition
	bustion products: Temperatures above the melting point may release alloy elements and metal
respi	es. ve equipment and precautions for fire-fighters: For a dust fire confined to a small area, use a rator approved for toxic dusts and fumes. Do not use water to extinguish fires around operations ving molten metal due to the potential for steam explosions.
Section 6	Accidental release measures
Whe air (F label Personal preca	dures: Product in solid form may be picked up by hand or other means to be placed into a container. In cleaning dust, use methods that minimize the dispersion of dust such as a high efficiency particulate HEPA) vacuum, wet dust mop, or wet clean-up. Put recovered material in a suitable, covered, and ed container. Itions, protective equipment and emergency procedures: Refer to Section 8. Drecautions: Refer to Section 12.
Section 7	Handling and storage
Insta asso weld Hygienic Practic of for Do n vacu Conditions for s	rocedures: This product does not require special safety precautions for handling prior to installation. Ilation and removal of the product may cause exposure to dusts and other materials or chemicals ciated with the installation (work) environment. Operations such as grinding, cutting, burning, and ing may generate dusts or fumes which may require special handling procedures. ces: Wash hands thoroughly after handling, and before eating or smoking. Smoking and consumption of or beverages should be restricted from areas where hazardous dust or chemical may be present. ot shake clothing, rags, or other items to remove dust. Dust should be removed by laundering or uming (with appropriate filters) the clothing, rags, or other items. cafe storage: Maintain good housekeeping to prevent exposure to materials and chemicals that may aminate or impair the quality of the product.
Section 8	Exposure controls/personal protection
Appropriate eng exha work minir cond Individual prote glass respi	ters: Refer to table in Section 3 for occupational exposure limit values. Jineering controls: When machining, heating, or melting, use adequate local (preferably) or general ust ventilation to ensure that concentrations of dusts or fumes do not exceed exposure limits. Keep place clean and dry (unless wet machining is being used to capture dust and fume). Train personnel to nize exposure to hazards during installation and replacement of product. On a regular basis, verify ition and proper function of equipment in which the product will be installed. ction measures: Use appropriate gloves to protect against physical hazards. Always wear safety ses with side shields and appropriate hearing protection when grinding or cutting. Use an approved rator, with the proper assigned protection factor, whenever airborne concentrations of hazardous bonents exceed exposure limits listed in Section 3. Workers should wash before meals and leaving
Section 9	Physical and chemical properties
Appearance Odor: Boiling point an Melting point: Flash point: Evaporation rate Flammability: Vapor pressure: Vapor density:	Not flammable



CenterLine® RWMA Class 2 Copper Resistance Welding Electrodes

Density: Solubility in water:	8.9 g/cm ³ (0.32 lb/in ³) Insoluble
Note: Thes	se are typical values and do not constitute a specification.
Section 10 S	Stability and reactivity
Reactivity: Chemical Stability:	Copper may react with acetylene gas to form copper acetylides, which are sensitive to shock. Copper may react with strong acids to generate explosive gas (e.g., hydrogen). Stable under normal use conditions
Conditions to avoid:	 lous reactions: May react with strong acids. Contact of dust with strong oxidizers may cause fire or explosion. Temperatures > 500 C (930 F), which may soften the copper alloy. als: Dust is explosively incompatible with sodium azide.
-	osition products: The melting of this product may release alloy elements and metal oxides.
Section 11 T	oxicological information
Under normal handl irritation to eyes and Inhalation may caus breathing, congestic	b the physical, chemical and toxicological characteristics ling and use, exposure to product presents few health hazards. Dusts may cause mechanical d skin. Ingestion may cause transient irritation of throat, stomach and gastrointestinal tract. se coughing, nose and throat irritation, and sneezing. Higher dust exposures may cause difficulty on, and chest tightness.
Possible effects by r	ate effects and also chronic effects from short and long term exposure
Inhalation: B di ca fe re	reathing metal dust may worsen symptoms of individuals with pre-existing chronic respiratory isease. Follow exposure guidelines for copper dust and fume. Acute exposure to dust or fume may ause upper respiratory tract irritation, metallic taste in mouth, nausea, fatigue, and/or metal fume ever. Breathing copper dust may worsen symptoms of individuals with pre-existing chronic espiratory disease. Inhaling particulate containing lead.
Skin absorption: M	Copper can cause some irritation with possible discoloration of skin. Metal dust exposure in hot, humid atmospheres may cause skin irritation. Allergic contact dermatitis is rarely encountered.
le Ingestion: In is	present as dust, copper may cause irritation, discoloration, and damage. As a foreign body in the ens, copper dust may cause a dense cataract and discolor the lens. Ingestion of significant amounts of welding electrodes is unlikely. If copper is swallowed and person is conscious, give large quantities of water to drink. Get medical attention as soon as possible.
Numerical measures While no toxicity dat constituents:	ta is available for the electrode alloy(s), the following data has been determined for the material
Chromium:LD _{Lo} Grou (carc	b, mouse, oral >5,000 mg/kg. b, female rat, oral, 16 mg/kg. The IARC lists metallic chromium and chromium[III] compounds as up 3 (not classifiable as to its carcinogenicity to humans). Chromium[VI] is listed under Group 1 cinogenic to humans).
Silicon: LD ₅₀ Lead: LD ₅₀	n, not available. n, rat, oral >5,500 mg/kg. n, rat, oral >3,160 mg/kg. n, rat, oral >160 mg/kg. IARC lists lead and its inorganic compounds under its Group 2A (probably inogenic to humans).
Section 12 E	cological information
Copper metal is relative	vely insoluble in water and, therefore, generally has low bioavailability. This product is not

expected to present an environmental hazard. Avoid releasing dusts and fumes into the environment.



CenterLine® RWMA Class 2 Copper Resistance Welding Electrodes

 Page:
 4 of 4

 SDS No.:
 CWL-C103-BE

 Revised:
 03MAY2021

 Replaces:
 CWL-C103-AE

 14MAY2018
 14MAY2018

Product should be recycled as scrap copper whenever possible and may be treated as general industrial solid waste if permitted by federal, state, and local disposal regulations.

Section 14 Transport information

UN number:	Not applicable
UN proper shipping name:	Not applicable
Transport hazard class(es):	
• • • • • • • • •	1.1
Packing group number:	Not applicable
Environmental hazards:	Not applicable
IMDG Code:	Not applicable
Transport in bulk:	Not applicable
Special precautions:	No special requirements are necessary in transporting this product.

Section 15 Regulatory information

This product has been classified in accordance with the hazard criteria of the Canadian Controlled Product Regulations (CPR) and the SDS contains all of the information required by the CPR.

The product is not classified as a health or environmental hazard under current legislation including Regulation (EC) No 1272/2008 and the Council Directives 67/548/EEC and 1999/45/EEC. No obligation exists to issue a safety data sheet according to REACH Art. 31.

Chromium, Copper, and Lead are on the list of toxic chemicals subject to the United States Environmental Protection Agency (EPA) Toxics Release Inventory (TRI) Program reporting requirements. The concentration of lead in this product is below the current de minimis level of 0.1%.

Hazardous Material Identification System (HMIS)

Health Hazard:	1
Flammability Hazard	0
Reactivity Hazard:	0
Maximum Personal Protection:	Е

Section 16 Other information

Key/Legend

noy/Logona	
ACGIH	= American Conference of Governmental Industrial Hygienists
CAS	= Chemical Abstracts Service (registry)
EINECS	= European Inventory of Existing Commercial Chemical Substances
HMIS	= Hazardous Materials Identification System
IARC	= International Agency for Research on Cancer
IMDG	= International Maritime Dangerous Goods
LD ₅₀	= lethal dose (50 percent kill)
LD _{Lo}	= lowest published lethal dose
OSHA	= Occupational Safety and Health Administration
PEL	= permissible exposure limit
TLV	= threshold limit value
TWA	= time weighted average
UN number	= Designation assigned by the United Nations Committee of Experts on the Transport of Dangerous Goods.
% WT	= percent weight

The information herein is given in good faith and based on technical data that CenterLine (Windsor) Ltd believes to be reliable. Since the conditions of use are outside our control, we assume no liability in connection with any use of this information and no warranty, expressed or implied is given. Contact CenterLine (Windsor) Ltd or its associates for additional information.

* End of SDS CWL-C103-BE *